

## LTspice Funktionstastenbelegung

**Keyboard Shortcut Map**

Click an item below and then press the new keyboard combination for the new short cut.

Schematic Symbol WaveForm Netlist

Place Component:	F2	Place Diode:	D
Draw Wire Mode:	F3	Draw Lines:	(none)
Place Netname:	F4	Draw Rectangles:	(none)
Delete Mode:	F5	Draw Circles:	(none)
Duplicate Mode:	F6	Draw Arcs:	(none)
Move Mode:	F7	Reset T=0:	0)
Drag Mode:	F8	Schematic Grid:	Ctrl+G
Undo:	F9	Rotate:	Ctrl+R
Redo:	Shift+F9	Mirror:	Ctrl+E
Place Comment Text:	T	Zoom Area:	Ctrl+Z
Place SPICE Directive:	S	Zoom Back:	Ctrl+B
Unconn. Pin Marks:	U	Halt Simulation:	Ctrl+H
Text Anchor Marks:	A	Run Simulation:	(none)
Place Ground:	G	Place BUS Tap:	(none)
Place Resistor:	R	Zoom to Fit:	Space
Place Capacitor:	C	View SPICE Error Log:	Ctrl+L
Place Inductor:	L		

Cancel Reset to Default Values OK

**Keyboard Shortcut Map**

Click an item below and then press the new keyboard combination for the new short cut.

Schematic Symbol WaveForm Netlist

Object Anchors:	O	Zoom Back:	Ctrl+B
Place Pin:	P	Zoom In:	Ctrl+Z
Delete Mode:	F5	Show Pin Table:	(none)
Duplicate Mode:	F6		
Move Mode:	F7		
Drag Mode:	F8		
Undo:	F9		
Redo:	Shift+F9		
Place Comment Text:	T		
Draw Lines:	L		
Draw Rectangles:	R		
Draw Arcs:	A		
Draw Circles:	C		
Rotate:	Ctrl+R		
Mirror:	Ctrl+E		
Attribute Editor:	Ctrl+A		
Attribute Window:	Ctrl+W		

Cancel Reset to Default Values OK

## LTspice Funktionstastenbelegung

